

In

Subject: comment NCSTAR 1-8
From: "Reiss, Alan" <areiss@panynj.gov>
To: <wtc@nist.gov>
Cc: "Bhol, Saroj" <sbhol@panynj.gov>

Good morning,

On page 1 of NCSTAR 1-8 exec. summary under emergency communications it says "**Lack of rigorous pre-emergency inspection and testing of radio communications systems within high-rise buildings to identify performance gaps and inadequacies.**" The system I had installed at the world trade center was fully tested and checked out by FDNY before being placed into service to verify expected performance both above & below grade. I am attaching a letter from FDNY to myself that was previously transmitted to NIST by our engineering department.

Alan Reiss
former dir. World Trade Center
Port Authority of NY & NJ
212 435 -3701
<<ltr - FDNY to A Reiss 011994.pdf>>



ltr - FDNY to A Reiss 011994.pdf